Container Loading Inspection Report

Customer :Susan Ling

Container :1X20FT

Cargo :Tower warmer

Location :On the roadside

Date of survey :17th June ,2011

THIS IS TO REPORT THAT

The undersigned China Pivot Sourcing Office, acting at the appointment and on behalf of the above mentioned Customer carried out container loading inspection of the above mentioned cargo and the following was ascertained:

1. FINDINGS:

Item	Finding
Shipper	Homtech Electrical Appliance Co.,Ltd
Commodity	Tower warmer
Packing	Packed in giftbox and master carton
Cargo was moved	by hands and small trucks (using pallets)
Container No. \ type	TCLU2238059/1x20ft
Truck No..	浙B31100
Seal Nos.	UASC1391468
Weather \air temperature	Light rain\ +15 C
Attending surveyor	Robin Yuan/China Pivot Sourcing Office

2, RESULT

Commodity	Cartons	Pieces	Remarks
Tower warmer	360	2160	Plan to load 2232pcs(372cantons) to a 20ft container,Actually loaded 2160pcs (360cartons)
Total:	**360**	**2160**	

This report reflects our finding on the dates and at the location stated only,
Does not certify any descriptions given and is issued without prejudice.

Loading equipments



The Missing point was added

Goods was moved by small truck

The place of loading (on the roadside)

Loading picture 1

Container No.

Before closing door

Sealing and sealing No.

After sealing

Door was closed