CHINA PIVOT SOURCING CO.,LTD

EXECUTIVE SUMMARY

To:	John
Attn.:	John
Product Name	coffee scoop
Vendor/Supplier:	Reason Enterprise Co., LTD.
Factory Name:	Reason Enterprise Co., LTD.
Factory Contact:	Rita Lin
Insp. Location:	Yang jiang.Guangdong
Inspection date:	July 05,2016
Time of insp.:	1st ☒ 2nd ☐ 3rd ☐

PO No.	Item No.	Quantity (Pcs)	Available Quantity			Sample Size (Pcs)
			Finished	Not packed	Not finished	
--	MS-SCOOP	5000	5000	0	0	200
Total:		5000	5000	0	0	200

Inspection standard: ANSI/ASQC Z1.4

Sampling plan: Single,
Normal Inspection level: II
AQL: Critical: 0 Major: 2.5 Minor: 4.0

	DEFECTS		
	Critical	Major	Minor
AQL:	0	2.5	4.0
Defects Found:	0	6	9
Max. Allowed:	0	10	14

Overall Conclusion

Category	**Result**	**Comment**
Quantity	**Passed**	
Product description /Style/Material/Color	**Passed**	
Workmanship	**Passed**	Remark 1
Testing/Checking	**Passed**	
Data measurement:	**Passed**	
Packaging	**Passed**	
Shipping mark:/Label	**Passed**	
Conclusion	**PASSED**	

Remarks:

1. For the handle back close to cup, the polishing line is vertical . Detail as below:

Declaration

This quality inspection report reflects our findings at time and place of service only. The report does not discharge or release the factory/seller/supplier from their commercial,legal or contractual obligations with buyers in respect of products provided by the factory/sellers/suppliers. This quality inspection report does not prejudice the buyer's right of claim toward sellers/suppliers for compensation for any found and/or hidden defects not detected during our service or occurring thereafter. The inspected samples are randomly drawn from the total quantity available; some other defects may exist in the remaining goods that are not inspected. The factory/seller/supplier is responsible for their product quality. The report does not evidence shipment

FOLLOWING PAGES ARE THE DETAILED INSPECTION RESULTS

WORKMANSHIP

No.	Defects Description	Picture	CRI	MAJ	MIN
1	defect-major-chipped edge		0	2	0
2	defect-major-obvious dent mark		0	4	0

3	defect-minor-poor polishing		0	0	7

					

4.	defect-minor-scratch mark		0	0	2
		Total Defect Found	**0**	**6**	**9**

TESTING/CHECKING

Item	Picture	Result	Comment
Barcode check		Passed	

Unit weight check		**Passed**	819g
capacity check		Passed	185-190ml

DATA MEASUREMENT

Item	Pictures	Result		
Carton size check		Passed 315x250x23omm		

Carton weight check		13.3kg		
Inner box size check		300x235x110mm		
Inner box weight check		6.3kg		

Product size check		292mm		
Product size check		39.69mm		
Product size check		25.39mm		

Product size check		13mm		
Product size check		6.1mm		
Product size check		T=1.78mm		

Product weight		819g		

PACKAGING

The 4 cartons for airfreight has no shipping label sticker



The 30 cartons for sea shipping has shipping label sticker, one shipping label sticker for one carton, total 30 cartons

2 inner box in one carton

no shipping mark on the inner box

75pcs /inner box, 2 inner boxes/carton, ,150pcs / carton.

SHIPPING MARKS/LABELS

OTHER PHOTOS

01 Finished product	
01 finshed carton (1)	02 finshed carton (2)
02 product	
01 master carton	02 main mark
	
03 side mark	04 side mark (2)

	
05 shipping label sticker (1)	06 shipping label sticker (2)
07 shipping label sticker (3)	08 shipping label sticker (4)
09 shipping label sticker (5)	10 shipping label sticker (6)

11 carton packing	14 inner box
16 unit packing (1) Each coffee scoop put in one polybag and was sealed	17 unit packing (2)
18 unit packing (3)	19 unit packing (4)

20 unit packing (5)	21 unit packing (6)
	
22 unit packing (7) sealed	23 unit packing (8)
	
24 barcode label on poly bag	25 unit view (1)

	
26 unit view (2)	27 unit view (3)
28 unit view (4)	29 unit view (5)
30 unit view (6)	31 unit view (7)

32 unit view (8)	33 unit view (9)
34 unit view (10)	12 5ply of carton
13 2box on one carton	15 3ply of inner box

03 on-site check	
01 barcode check (1)	02 barcode check (2)
	
03 barcode check (3)	04 capacity check (1)
	
05 capacity check (2)	06 capacity check (3)

07 carton size check (1)	08 carton size check (2)
	
09 carton size check (3)	10 carton weight check (1)
	
11 carton weight check (2)	12 inner box size check (1)

13 inner box size check (2)	14 inner box size check (3)
	
15 inner box weight check	16 unit size check (1)
17 unit size check (2)	18 unit size check (3)

19 unit size check (4)	20 unit size check (5)
21 unit size check (6)	22 unit weight check (1)
23 unit weight check (2)	24 unit weight check (3)

04 defects pictures	
01 defect-major-chipped edge (1)	02 defect-major-chipped edge (2)
03 defect-major-obvious dent mark (1)	04 defect-major-obvious dent mark (2)
	
05 defect-major-obvious dent mark (3)	06 defect-major-obvious dent mark (4)



07 defect-minor-poor polishing (1)



08 defect-minor-poor polishing (2)

09 defect-minor-poor polishing (3)

10 defect-minor-poor polishing (4)



11 defect-minor-poor polishing (5)

12 defect-minor-poor polishing (6)

13 defect-minor-poor polishing (7)

14 defect-minor-scratch mark (1)

15 defect-minor-scratch mark (2)

05 remark

01 remark 1 (1)



02 remark 1 (2)

03 remark 1 (3)	04 remark 1 (4)